

Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representativ	es Present During the Inspection:
OGM	Karl Houskeeper

Inspection Report

Permit Number:	C0150032 PARTIAL			
Inspection Type:				
Inspection Date:	Tuesday, January 18, 2011			
Start Date/Time:	1/18/2011 10:30:00 AM			
End Date/Time:	1/18/2011 3:00:00 PM			
Last Inspection:	Thursday, December 02, 2010			

Inspector: <u>Karl Houskeeper</u>,
Weather: <u>Cloudy, Temp. 31 Deg. F.</u>
InspectionID Report Number: <u>2617</u>

Types of Operations

Accepted by: jhelfric

1/26/2011

Permitee: GENWAL RESOURCES INC
Operator: GENWAL RESOURCES INC
Site: CRANDALL CANYON MINE

Address: PO BOX 910, EAST CARBON UT 84520-0910

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	6,235.80				
Total Disturbed	27.15				
Phase I					
Phase II					
Phase III					

Mineral Ownership

✓ Federal
✓ Underground

State
Surface

County
Loadout

Fee
Processing

Other
Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Checked in at the main office located at the West Ridge Mine prior to conducting the partial inspection at the Crandall Mine. Met with Dave Shaver at the West Ridge Mine and then proceed to the Crandall Mine by myself.

Inspector's Signature:

Nand R. Nousberger

Date

Tuesday, Januan 17011

Karl Houskeeper,

Permit Number: C0150032 Inspection Type: PARTIAL

Inspection Date: Tuesday, January 18, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	V		•	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	~		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	V		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
16.	o Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150032 Inspection Type: PARTIAL

Inspection Date: Tuesday, January 18, 2011

Page 3 of 3

2. Signs and Markers

Mine Identification sign is located at the entrance into the permit area. The sign contains the required information.

4.a Hydrologic Balance: Diversions

A portion of the undisturbed culvert that transcends the hillside has come loose and slid down the hill. The portion that came loose is now located at the base of the slope at the entrance into the main portion of the permit area. This segment needs to be reattached.

Snow has been placed into the lower diversion located below the iron treatment pond. The snow needs to be removed from the diversion. Contacted Dave Shaver by phone and e-mail to identify the problems and needed remedies.

8. Noncoal Waste

Numerous items of noncoal waste (trash) are located in front of the dumpster and are frozen in an ice sheet. The items need to be removed from the ice and placed into the dumpster. Dave Shaver was notified by phone and e-mail.